


POWER TOOLS

PRO 4125 A - RANDON ORBITAL SANDER

Packing	Power	Specifications	Mode
8	500W	125 MM	COLOR BOX



PRO 4125 A - ORBITAL SANDER

NO.	Name of Spare parts
1	Left Fastener
2	PCB Assembly
3	Left housing
4	Switch Pole
5	Switch
6	Capacitor
7	Connection Pole
8	Lamp Chimney
9	Lamp
10	Cord protector
11	Power plug and Cord
12	Dust Cover
13	Dust Box
14	Right Housing
15	Right Fastner
16	Stator
17	Inductance
18	Carbon Brush Assembly
19	Bearing
20	Rotor
21	Cooling fan
22	Bearing
23	Fan
24	Copulate Block
25	Bearing Seat
26	Bearing
27	Eccentricity Block
28	Washer
29	Screw
30	base
31	Froth
32	Screw
33	Washer
34	Screw